

Release: **3.0.5** **2020-09-16**

Updater:

- Update_DLKPro_3.0.5_20200916.exe

GIT revision:

- 64E0AD9ED9B5D5849382B29EB846EC67E05F20E4

Changes:

- Optimize RTC synchronization with Gen 2 TCOs.
- Fix issue with Signature checking.
- Add using VRN and VRN Nation from Calibration purpose 5 "VRN by company card" for French file names.

Parts:

• Module	Version	Datum
• Download Tools	3.0.5	2020-09-16
• Breach	3.0.0	
• Reminder	3.0.0	
• Support	3.0.2	
• Configuration	3.0.0	
• Viewer	3.0.0	
• Firmware	3.0.7	2020-04-22

Release: **3.0.4** **2020-04-24**

Updater:

- Update_DLKPro_3.0.4_20200424.exe

GIT revision:

- B99F96383C97253D9E95D39CC9BA0D4B4D0B644F

Changes:

- Change back for the not yet published new French filename extensions back to *.C1B and *.V1B.
IMPORTANT for France!

Parts:

• Module	Version	Datum
• Download Tools	3.0.4	2020-04-24
• Breach	3.0.0	
• Reminder	3.0.0	
• Support	3.0.1	
• Configuration	3.0.0	
• Viewer	3.0.0	
• Firmware	3.0.6	2020-04-22

Release: 3.0.3 2020-03-16

Updater:

- Update_DLKPro_3.0.3_20200316.exe

GIT revision:

- 4F54F0F3A60A45D37F5CCB595557F4667730DAAD

Changes:

- Improving the interoperability between the DLK Pro and the new DTCO generations.
- Add new Code signing certificate

Parts:

• Module	Version	Datum
• Download Tools	3.0.3	2020-03-16
• Breach	3.0.0	
• Reminder	3.0.0	
• Support	3.0.1	
• Configuration	3.0.0	
• Viewer	3.0.0	
• Firmware	3.0.5	2020-03-13